

#### **DEPARTMENT OF THE NAVY**

COMMANDER
HELICOPTER TACTICAL WING
U.S. PACIFIC FLEET
NAS NORTH ISLAND P.O. BOX 357096
SAN DIEGO, CALIFORNIA 92135-7096

COMHELTACWINGPACINST 4440.2C

MAR 0 6 1996

### COMHELTACWINGPAC INSTRUCTION 4440.2C

Subj: DELAYED TURN-IN POLICY AND PROCEDURES

Ref:

(a) OPNAVINST 4440.25

(b) OPNAVINST 4790.2G

Encl:

(1) Delayed Turn-in Request (CHTWP Form 4440/1)

- (2) Consolidated Remain-in-Place List (CRIPL) Change Request Form (CHTWP Form 4440/2)
- 1. <u>Purpose</u>. To establish policy and procedures for the delayed turn-in of repairable aircraft components that are not listed in the Consolidated Remain-in-Place List (CRIPL).
- 2. Cancellation. COMHELTACWINGPACINST 4440.2B.
- 3. <u>Discussion</u>. To be eligible for Remain-in-Place (RIP) designation, a component must be a repairable item assigned material control Code D, E, G, H, Q or X and must satisfy one or more of the following conditions:
- a. <u>Safety (non-flight)</u>. With items removed, aircraft is in an unsafe configuration, i.e., weight and balance, structural limits, personnel hazard.
- b. Mobility. With items removed, aircraft cannot immediately be moved in the event of an emergency.
- c. <u>Maintenance</u>. Removal of the item involves exchange of numerous fittings or linkages that expose the aircraft to water intrusion, corrosion or mechanical damage or precludes turn-up to facilitate other maintenance.
- d. <u>Partial Mission Capable Supply (PMCS) Flight.</u> Removal of the item precludes flight but retention permits flight with degraded condition of installed system.
- 4. Scope. The policy and procedures in this instruction apply to all COMHELTACWINGPAC aircraft squadrons and activities engaged in aviation supply and logistics support.
- 5. <u>Background</u>. References (a) and (b) set forth policy for the establishment and maintenance of a CRIPL for depot-level and field-level repairables. This instruction amplifies references (a) and

# COMHELTACWINGPACINST 4440.2C

- (b), provides specific local RIP policy and procedures in order to strictly enforce the one-for-one exchange policy for all repairable items, improves validity of the CRIPL list, and establishes the only locally authorized procedures for requesting delayed turn-ins.
- 6. Action. Non-NAVAIR approved RIP items; items requiring local RIP approval will be processed as follows:
- a. An E-7 or above from the requisitioning activity will initiate a request via phone to the appropriate COMHELTACWINGPAC Maintenance Class Desk who will review the request and all pertinent information.
- b. If the request is approved, the Maintenance Class Desk will sign enclosure (1) to notify the Supply Department and Component Control Section (CCS) Officer of the authorization for delayed turn-in. The squadron involved will complete enclosure (1) and provide a copy to the NAS Supply Department Component Control Section (CCS) Officer and will serve as proof of authorization.
- c. The requesting activity will order via normal supply procedures indicating "COMHELTACWINGPAC Authorized Delayed Turn-in (name of approving Class Deck Officer)" in the reference block.
- d. Approval of a locally authorized delayed turn-in indicates the possibility that an item should be on the NAVAIR authorized CRIPL list. When applicable, the requesting squadron is required to submit a CRIPL nomination request, enclosure (2).
- e. Upon receipt of requested material, the customer will turn in retrograde to supply within 24 hours.

7. Forms. This instruction institutes CHTWP Form 4440/1 and 4440/2. Both forms are stocked and reproduced locally.

D. A. MAWHINNEY

Distribution: COMHELTACWINGPACINST 5216.1C (CH-1) List I, II

# MAR 0 6 1998

## DELAY TURN-IN REQUEST

SQUADRON/ACTIVITY		DATE	
DOC NO	JCN	CN	
COGNSN			
FSCM	P/N		
NOMENCLATURE		ICRL CO	DE
BUNO	AVAILABILITY: NAS	NI	ASO
ESTIMATED TURN-IN	DATE		
	REQUEST FOR DELAYED TU		
		W	
ENDORSEMENTS:			
SQUADRON/ACTIVITY	MO/MMCO/MCPO	DATE	PHONE
TYPE AIRCRAFT WING OR DESIGNATED REPR	MAINTENANCE OFFICER	DATE	PHONE
or papionning KEFK	TOUT TALL I		
			٠

ASD DIRECTOR/DEPUTY DIRECTOR
CCS OFFICER

# MAR 0 6 1898

## CONSOLIDATED REMAIN-IN-PLACE LIST (CRIPL) CHANGE REQUEST FORM

From:	
Via: (0	ommander, Naval Air Systems Command (AIR-4114) Originator's TYCOM/ACC) Wing)
_	EQUEST FOR CHANGE TO CONSOLIDATED REMAIN-IN-PLACE LIST CRIPL)
Ref: (a	a) OPNAVINST 4440.25
	accordance with reference (a), it is requested that the g item be added to/deleted from the RIP List:
a. <i>i</i>	Application (aircraft)
b. 1	Nomenclature
c. 1	NSN
d. :	Part Number
following	<u>rification for addition</u> . Must specify one or more of the g criteria and include additional amplifying details in h 4 below.
unsafe co	<u>Safety (non-flight)</u> . With item removed, aircraft is in an onfiguration (weight and balance, structural limits, 1 hazard).
	Mobility. With item removed, aircraft cannot immediately in the event of an emergency.
numerous intrusion	<u>Maintenance</u> . Removal of the item involves exchange of fittings or linkages; exposes the aircraft to water n, corrosion or mechanical damage; or precludes turn-up to te other maintenance.

d. PMCS Flight. Removal of the item precludes flight but retention permits flight with degraded mode condition of installed

- 3. Reason for deletion.
- 4. Remarks.

system.